

VEHICLE INSPECTION REPORT

PO19SOJ

Fiat Doblo 1.3 MULTIJET 95PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/03/2019

Year 2019

Mileage 129,941 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006M41047

Body Style Panel Van L1

MOT Due 02/03/2026

CAP Clean £2,425.00

CAP Average £2,125.00

CAP Below £1,725.00

Gearbox MANUAL

Gears 5

COLLECTED AS NON RUNNER - BATTERY & GEARBOX ISSUES SIDE LOADING DOOR

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Door nsr
Chipped
1 To 5



2: Sill os
Scratched
Over 25mm Thru Paint



3: Sill os
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK